





## SmartyCam 3 Corsa Release history

Page 1

Version	Date	Change/additions
01.10.04	Jan, 19th 2024	<ul> <li>Fixed graphical dot behaviour in accelerometer overlay when sensor data is missing</li> <li>Fixed Lap distance reset when starting a new recording</li> </ul>
01.09.04	Nov, 28th 2023	<ul> <li>Added 'Lap Distance' to the list of channels</li> <li>Predictive Lap Time, Best Lap Time and +/- best lap time now show consistent information</li> </ul>
01.09.01	Sep, 22nd 2023	■ Reduced boot time
01.08.07	Sep, 15th 2023	<ul> <li>Improved interoperability with latest Firmware versions for GPS09 receivers</li> <li>Improved behavior in case of unstable Input Voltage</li> </ul>
01.08.04	Sep, 4th 2023	■ Improved detection of overheating conditions
01.08.02	Jul, 24th 2023	<ul> <li>Integrated GPS 09 B firmware version 02.40.68 to improve CAN network communication</li> <li>Fixed interoperability issues with AiM CAN devices when more than one expansion in connected to the AiM CAN Bus</li> </ul>
01.07.12	Jun, 30th 2023	<ul> <li>Added support for MXm V2 devices</li> <li>Improved lap detection when working with ECUs</li> <li>Added recording of measures for internal voltages</li> </ul>
01.07.07	Jun, 8th 2023	<ul> <li>Increased number of available exposure options</li> <li>Added support to Flagtronics FT-200 systems (requires Race Studio 3 version 3.59.51 to be configured)</li> </ul>
01.07.03	May, 5th 2023	<ul> <li>Added icon for current power status in camera display</li> <li>Fixed interoperability issue with GPS09C</li> <li>Fixed CAN Silent Mode when connected to ECU (N/A for SC3 Sport model)</li> </ul>
01.06.09	Apr, 19th 2023	■ Improved reliability of firmware update process







## SmartyCam 3 Corsa Release history

Page 2

Version	Date	Change/additions
01.06.07	Apr, 18th 2023	<ul> <li>Added support for GP PRO models</li> <li>Support for most recent GPS models</li> <li>Fixes to CAN protocol definitions</li> </ul>
01.05.12	Apr, 7th 2023	<ul> <li>Bug fix for disabling the 120 Ohm CAN bus terminating resistor</li> <li>Bug fix for steering pos graphic widget</li> </ul>