Version	Date	Changes – Additions
33.40	September 13th 2010	▪ Improved firmup management ▪ Added GPS maps saving in firmup management
33.37	July 30th 2010	Added Upgrade for MyChron Expansion
33.34	June 3rd 2010	Added Management of MyChron Expansion
33.33	March 5th 2010	Fixed bug on upgrade Firmware GPS with SmartyCam connected
33.32	February 23th 2010	Management of GPS05
33.31	November 24th 2009	Management GPS04
33.30	April 28th 2009	Added management of SmartyCam
33.28	July 1st 2008	Added sub-revision management in Firmup
33.27	April 24th 2008	Fixed problem on upgrade FW with some old M4 firmware versions
33.25	February 22nd 2008	Fixed bug on M4 Picture Manager
33.23	February 4th 2008	Added compatibility with MC4 660
33.19	December 12th 2007	▪ Swapped "Upgrade BOOTER" with "Upgrade LANGUAGES"; the Languages will be upgraded immediately after the upgrade of M4 ▪ At the end of FIRMUP " END " will appear (and stay for 10" before Power off with a RED-LED blinking) if the operation is terminated correctly ▪ When an error occurs, a message ERROR with the code of the error appears. ▪ At the end of "Download Data" or "No New Data" or "Memory Empty", the RED-LED starts blinking for 10" then the M4 is switched off ▪ Every operation (except the BOOTER upgrade) can be reinitialized, in the bad case of an involontary interruption (battery, cable, ecc.). Specially the eBOX upgrade can be easily restarted (even if the Firmware is lost)
33.18	June 8th 2007	▪ The Upgrade procedure of M4/EBOX/GPS (LAMBDA is not yet available) from datakey, shows on the m4 display the status of each operation and blinks the LEDs for further feedback ▪ At the end of Upgrade " -- E N D --" is displayed and after 5 seconds the system is powered off automatically ▪ The Booter of M4 is upgraded to the new version 2.06 for a more robust start up on RPM signal (same as on M4)
33.15	March 23rd 2007	Updated with new Firmup (4.05.16) functions
33.11	February 22nd 2007	Fixed bug on external flash memories that were not completely erased by manufacturer
33.10	February 14nd 2007	Added management of GPS Module
33.08	May 11th 2006	Added function to erase data stored in the DataKey from the PC
33.07	May 4th 2006	Fixed bug to avoid failure in the updating process of MyChron 4 firmware