

Solo 2 DL Release history

Page 1

Version	Date	Change/additions
02.26.55	Mar, 14th 2019	<ul style="list-style-type: none">▪ Increased channel frequencies for selected ECUs (in particular K-line- and RS232- based ones) <p>External modules</p> <p>No changes</p>
02.26.50	Jan, 18th 2019	<ul style="list-style-type: none">▪ Performance Race Mode: fix wrong units of measurement in data recall page (MPH and ft were shown but values were in km/h and m)▪ ECU: support Adaptronics and Motec M4 ECU drivers <p>External modules</p> <p>No changes</p>
02.26.38	Dec, 14th 2018	<ul style="list-style-type: none">▪ Fixed calculated Performance Time▪ Fixed "+/- Best Time" display visualization▪ Added "laptime resume visualization" crossing the finish (it can be disabled by menu option) <p>External modules</p> <p>No changes</p>
02.26.12	Oct, 30th 2018	<ul style="list-style-type: none">▪ Support for Can Optical Lap(IRM_42)▪ CAN network fixes▪ 100Hz CAN output management <p>External modules</p> <p>No changes</p>
02.26.06	Oct, 5th 2018	<ul style="list-style-type: none">▪ Fixed bug on backlight set in OFF mode▪ Fixed power off for external modules when Solo 2 DL is in charging mode▪ Fixed bug on Digital output priority handling <p>External module</p> <ul style="list-style-type: none">▪ 25.47 Lambda

Solo 2 DL Release history

Version	Date	Change/additions
02.24.05	Sep, 21st 2018	<ul style="list-style-type: none">▪ Custom pages with pressure channels: unit of measure is selectable for each individual channel▪ Performance race: fixed missing performance entry in data recall▪ Fixed bug in led bar handling with predictive lap time <p>External modules</p> <p>No changes</p>
02.22.81	Jul, 26th 2018	<ul style="list-style-type: none">▪ Fixed power consumption in low power mode (board REV00)▪ Fixed multiplexed CAN protocols management <p>External modules</p> <p>No changes</p>
02.22.67	Jun, 29th 2018	<ul style="list-style-type: none">▪ Added automatic start data recall at the end of the new test recorded▪ Fixed bug in Predictive time calculation that in some cases, with high speed applications, caused bad behavior▪ Fixed bug in System Info menu in "Hw revision" text display <p>External modules</p> <p>No changes</p>
02.22.65	Jun, 22nd 2018	<ul style="list-style-type: none">▪ Improved suspend/powerup handling▪ Support for board revisions C and E <p>External modules</p> <p>No changes</p>
02.22.58	May, 31st 2018	<ul style="list-style-type: none">▪ Support of k-line protocols <p>External modules</p> <p>No changes</p>
02.22.52	May, 18th 2018	<ul style="list-style-type: none">▪ Added "All Laps" data recall page and "Speed graph with track" data recall page▪ Added in "Wi-Fi" menu the possibility to choose the Wi-Fi channel to use instead of a random selection at boot▪ Fixed issue that, sometimes, after a shut down of the system, didn't allow to switch on again the Solo 2 DL <p>External modules</p> <ul style="list-style-type: none">▪ 25.47 Lambda