



MXS Strada Release history

Version	Date	Change/additions
01.24.14	Mar 24th 2017	<ul style="list-style-type: none">▪ Fixed bug that caused no data from channels with hysteresis <p>External modules</p> <ul style="list-style-type: none">▪ 35.56 GPS Module▪ 25.46 Lambda▪ 40.56 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface
01.24.13	Mar 24th 2017	<ul style="list-style-type: none">▪ Improved accelerometer support: better filtering and uniform sign convention on various devices▪ Fixed occasional spikes on accelerometer channels <p>External modules</p> <ul style="list-style-type: none">▪ 35.56 GPS Module▪ 25.46 Lambda▪ 40.56 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface

MXS Strada Release history

Page 2

Version	Date	Change/additions
01.24.00	Jan 26th 2017	<ul style="list-style-type: none">▪ Fixed issue that caused CAN network malfunction when remote button device is in the network <p>External modules</p> <ul style="list-style-type: none">▪ 35.56 GPS Module▪ 25.46 Lambda▪ 40.56 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface
01.22.99	Jan 19th 2017	<ul style="list-style-type: none">▪ Added management of GPS position accuracy measure for display and CAN output▪ Fixed bug in "Backlight" menu voice (icon missed) <p>External modules</p> <ul style="list-style-type: none">▪ 35.56 GPS Module▪ 25.46 Lambda▪ 40.56 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface
01.22.94	Dec 5th 2016	<ul style="list-style-type: none">▪ No changes <p>External modules</p> <ul style="list-style-type: none">▪ 35.56 GPS Module▪ 25.46 Lambda: fixed bug that caused shifted lambda samples▪ 40.56 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface

MXS Strada Release history

Version	Date	Change/additions
01.22.92	Nov 29th 2016	<ul style="list-style-type: none">▪ Minor improvements <p>External modules</p> <ul style="list-style-type: none">▪ 35.56 GPS Module: improvements in GPS measurements available to SmartyCam overlay▪ 25.44 Lambda▪ 40.56 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface
01.22.86	Nov 15th 2016	<ul style="list-style-type: none">▪ Added IRM CAN LAP support <p>Warning: this firmware release requires Race Studio 3 ver. 3.10.10 or higher.</p> <p>External modules</p> <ul style="list-style-type: none">▪ 35.54 GPS Module: improved satellites fix▪ 25.44 Lambda: added keep alive support▪ 40.56 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface
01.22.82	Oct 11th 2016	<ul style="list-style-type: none">▪ Speed up USB transfer▪ Speed up display pages loading at the startup▪ Fixed bug in GPS lap management that in some cases caused loss of laps detected <p>Warning: this firmware release requires Race Studio 3 ver. 3.10.10 or higher.</p> <p>External modules</p> <ul style="list-style-type: none">▪ 35.50 GPS Module▪ 25.42 Lambda▪ 40.56 Channel Expansion/TC Hub: improved analogic channels acquisition▪ 70.01 Remote buttons interface
01.22.74	Sep 15th 2016	<ul style="list-style-type: none">▪ Fixed alarms functionality based on acquisition channels under encryption▪ Fixed message alarms that sometimes were partially or totally erased <p>Warning: this firmware release requires Race Studio 3 ver. 3.10.10 or higher.</p> <p>External modules</p> <ul style="list-style-type: none">▪ 35.50 GPS Module▪ 25.42 Lambda▪ 40.55 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface

MXS Strada Release history

Version	Date	Change/additions
01.22.60	Jul 25th 2016	<ul style="list-style-type: none">▪ Fixed: clear alarm by remote buttons▪ Fixed: alarm hysteresis condition▪ Minor bugfixes and improvements <p>Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher.</p> <p>External modules</p> <ul style="list-style-type: none">▪ 35.50 GPS Module▪ 25.42 Lambda▪ 40.55 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface
01.22.16	Jun 17th 2016	<ul style="list-style-type: none">▪ Fixed display issue when 8 pages are configured▪ Fixed bug on Shift Light management▪ Minor improvements <p>Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher.</p> <p>External modules</p> <ul style="list-style-type: none">▪ 35.50 GPS Module▪ 25.42 Lambda▪ 40.55 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface
01.22.14	Jun 10th 2016	<ul style="list-style-type: none">▪ New track management, compatible with the MyChron5 one▪ Test data recall <p>Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher.</p> <p>External modules</p> <ul style="list-style-type: none">▪ 35.50 GPS Module▪ 25.42 Lambd▪ 40.55 Channel Expansion/TC Hub▪ 70.01 Remote buttons interface