



## EVO4S Release history

Version	Date	Change/additions
<b>01.24.45</b>	Apr 19th 2017	<ul style="list-style-type: none"><li>▪ Fixed bug in AiM digital speed channels when 'Ang Velocity' is selected (i.e. RPM setting)</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.56</b> GPS Module</li><li>▪ <b>25.46</b> Lambda</li><li>▪ <b>40.56</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>
<b>01.24.38</b>	Apr 5th 2017	<ul style="list-style-type: none"><li>▪ Support for Formula Steering Wheel 3 configuration</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.56</b> GPS Module</li><li>▪ <b>25.46</b> Lambda</li><li>▪ <b>40.56</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>
<b>01.24.34</b>	Mar 24th 2017	<ul style="list-style-type: none"><li>▪ Added GS-Dash management</li><li>▪ Improved accelerometer support: better filtering and uniform sign convention on various devices</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.56</b> GPS Module</li><li>▪ <b>25.46</b> Lambda</li><li>▪ <b>40.56</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>



## EVO4S Release history

Version	Date	Change/additions
<b>01.24.00</b>	Jan 26th 2017	<ul style="list-style-type: none"><li>▪ Fixed issue that caused CAN network malfunction when remote button device is in the network</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.56</b> GPS Module</li><li>▪ <b>25.46</b> Lambda</li><li>▪ <b>40.56</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>
<b>01.22.99</b>	Jan 19th 2017	<ul style="list-style-type: none"><li>▪ Added management of GPS position accuracy measure for CAN output</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.56</b> GPS Module</li><li>▪ <b>25.46</b> Lambda</li><li>▪ <b>40.56</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>
<b>01.22.94</b>	Dec 5th 2016	<ul style="list-style-type: none"><li>▪ No changes</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.56</b> GPS Module</li><li>▪ <b>25.46</b> Lambda: fixed bug that caused shifted lambda samples</li><li>▪ <b>40.56</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>
<b>01.22.92</b>	Nov 29th 2016	<ul style="list-style-type: none"><li>▪ Minor improvements</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.56</b> GPS Module: improvements in GPS measurements available to SmartyCam overlay</li><li>▪ <b>25.44</b> Lambda</li><li>▪ <b>40.56</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>



## EVO4S Release history

Version	Date	Change/additions
<b>01.22.86</b>	Nov 15th 2016	<ul style="list-style-type: none"><li>▪ Added IRM CAN LAP support</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.54</b> GPS Module: improved satellites fix</li><li>▪ <b>25.44</b> Lambda: added keep alive support</li><li>▪ <b>40.56</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>
<b>01.22.82</b>	Oct 11th 2016	<ul style="list-style-type: none"><li>▪ Speed up USB transfer</li><li>▪ Fixed bug in GPS lap management that in some cases caused loss of laps detected</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.50</b> GPS Module</li><li>▪ <b>25.42</b> Lambda</li><li>▪ <b>40.56</b> Channel Expansion/TC Hub: improved analogic channels acquisition</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>
<b>01.22.74</b>	Sep 15th 2016	<ul style="list-style-type: none"><li>▪ Fixed alarms functionality based on acquisition channels under encryption</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.50</b> GPS Module</li><li>▪ <b>25.42</b> Lambda</li><li>▪ <b>40.55</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>
<b>01.22.60</b>	Jul 25th 2016	<ul style="list-style-type: none"><li>▪ Fixed: alarm hysteresis condition</li><li>▪ Minor bugfixes and improvements</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.50</b> GPS Module</li><li>▪ <b>25.42</b> Lambda</li><li>▪ <b>40.55</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>



## EVO4S Release history

---

Version	Date	Change/additions
<b>01.20.68</b>	Jul 1st 2016	<ul style="list-style-type: none"><li>▪ Fixed: handling of enabling /disabling of CAN termination resistance</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.50</b> GPS Module</li><li>▪ <b>25.42</b> Lambda</li><li>▪ <b>40.55</b> Channel Expansion/TC Hub</li><li>▪ <b>70.01</b> Remote buttons interface</li></ul>