



## MXS 1.2 Release history

Version	Date	Change/additions
<b>02.26.55</b>	Mar, 14th 2019	<ul style="list-style-type: none"><li>▪ Improved ADC accuracy</li><li>▪ GPS page skipped when the vehicle is moving</li><li>▪ Increased channel frequencies for selected ECUs (in particular K-line- and RS232- based ones)</li><li>▪ Fix bug on clear alarm by keypress</li><li>▪ Fix display bug which could lead to device resets with heavy configurations (multiple pages)</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.26.53</b>	Feb, 14th 2019	<ul style="list-style-type: none"><li>▪ Fixed inertial platform orientation</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>02.26.51</b> Shift Light Module<ul style="list-style-type: none"><li>▪ Fixed issues with some ECUs</li></ul></li></ul> <p>No changes for the other modules</p>
<b>02.26.50</b>	Jan, 18th 2019	<ul style="list-style-type: none"><li>▪ Digital inputs</li><li>▪ Support for Memory Module, Strada Logger and GS-Dash</li><li>▪ ECU: support Adaptronics and Motec M4 ECU drivers</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>01.26.48</b> Memory Module and Strada Logger</li><li>▪ <b>01.26.47</b> GS-Dash</li></ul>

## MXS 1.2 Release history

Version	Date	Change/additions
<b>02.26.35</b>	Dec, 5th 2018	<ul style="list-style-type: none"><li>▪ Added management of Shift Light Module</li><li>▪ Added the support for auto brightness levels configuration (day brightness level, night brightness level and threshold are now fully configurable)</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.26.12</b>	Oct, 30th 2018	<ul style="list-style-type: none"><li>▪ Support for CAN Optical Lap (IRM_42)</li><li>▪ CAN network fixes</li><li>▪ 100Hz CAN output management</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.26.08</b>	Oct, 15th 2018	<ul style="list-style-type: none"><li>▪ Improved synchronization of GPS data</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>35.60</b> GPS Module</li><li>▪ <b>25.47</b> Lambda</li><li>▪ <b>40.61</b> Channel Expansion/TC Hub</li><li>▪ <b>70.03</b> Remote buttons interface</li></ul>
<b>02.26.06</b>	Oct, 5th 2018	<ul style="list-style-type: none"><li>▪ Fixed bug on Digital output priority handling</li></ul>
<b>02.26.01</b>	Oct, 1st 2018	<ul style="list-style-type: none"><li>▪ Added support for rear cam and rear cam configuration menu</li><li>▪ Fix on units of measure visualization</li></ul>
<b>02.24.04</b>	Sep, 21st 2018	<ul style="list-style-type: none"><li>▪ Support for RS232 protocols</li></ul>
<b>02.22.96</b>	Sep, 11th 2018	<ul style="list-style-type: none"><li>▪ Fixed potentiometers calibration</li><li>▪ Improved display management when ECU CAN stream has very few fields</li></ul>
<b>02.22.93</b>	Sep, 4th 2018	<ul style="list-style-type: none"><li>▪ Support for fuel set/reset using Race Studio 3</li><li>▪ Fix on visualized unit of measure</li></ul>
<b>02.22.81</b>	Jul, 27th 2018	<ul style="list-style-type: none"><li>▪ Fixed Remote button interface compatibility</li><li>▪ Fixed multiplexed CAN protocols management</li></ul>